COVID-19 Infection Prevention Measures On the Jobsite

The following measures may help prevent transmission of COVID-19 on construction job sites.

R	Stay home if you are sick. DO NOT WORK.
	Wash hands frequently or provide alcohol-based hand rubs containing at least 60% alcohol.
	Cover coughs and sneezes.
°⇔°	Practice social distancing — including maintaining 6 feet between each worker.
	Reduce the size of work crews to the extent safely possible and LIMIT all in-person meetings.
	Minimize ride-sharing. While in vehicle, employees must ensure adequate ventilation.
×	Avoid sharing tools with co-workers, if possible.
K	Clean and disinfect frequently used tools, equipment, and frequently touched surfaces (door handles, handrails, machinery controls, cell phones, tablets) on a regular basis.
R. K.	If N95 respirator masks are not available, minimize dust and airborne contaminants by using engineering and work practice controls.
	Use proper personal protective equipment (PPE) when cleaning and disinfecting, such as gloves and eye protection.
TOMPKINS COUNTY	



